

NO: 14-03-96

SUBJECT: Rusty Fuel Filler Bezel Screws

DATE: May 10, 1996

SYMPTOM/CONDITION:

The fuel filler bezel screws may rust prematurely.

DIAGNOSIS:

Inspect the screws. If the screws appear rusty, perform the Repair Procedure.

PARTS REQUIRED:

Quantity	Part No.	Description
4	0153651	Screws

REPAIR PROCEDURE:

This bulletin involves replacing the fuel filler bezel attaching screws.

Remove the four fuel filler bezel attaching screws and replace them with P/N 0153651. Tighten the screws to 2.8 Nm (25 in. lbs).

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No.	Time
14-60-15-90	0.2 Hrs.

FAILURE CODE:

Code	Description
P8	New Part