

**NO: 14-05-97**

**SUBJECT: Slow Fuel Fill**

**DATE: Jun. 27, 1997**

**NOTE: THIS BULLETIN APPLIES TO VEHICLES BUILT PRIOR TO DECEMBER 22, 1996 (MDH 12-22-XX).**

**SYMPTOM/CONDITION:**

The fuel tank may be slow to fill. The gasoline pump may repeatedly shut off while filling. A fuel tank with an improved venting system has been released which will improve this condition.

**DIAGNOSIS:**

If slow fuel fill complaints are received on vehicles built prior to December 22, 1996, (MDH 12-22- XX) perform the Repair Procedure.

**PARTS REQUIRED:**

Quantity	Part No.	Description
1	52018687AB	Fuel Tank - 15 gallon
1	52018768AB	Fuel Tank - 19 gallon
1	52127505AC	Vent Hose

**REPAIR PROCEDURE:**

This bulletin involves Installing a revised fuel tank.

1. Relieve the fuel pressure from the system, drain the fuel from the tank and remove the fuel tank from the vehicle using the procedures outlined in group 14 of the 1997 Wrangler Service Manual (publication number 81-370-7148).
2. Install the new fuel tank and vent hose.
3. Fill the tank with the fuel previously removed.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No.	Time
14-60-02-92	1.4 Hrs.

**FAILURE CODE:**

Code	Description
P8	New Part